


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-094	Smoke	9/2/2008	ADS/TM	S09CC1022MH	Dry	Yes	944.79



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-094	Smoke	9/2/2008	ADS/TM	S09CC1022MH	Dry	Yes	944.79

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11AA1005G1	S11AA1005MH	S11CC1006MH	238.2774	8
S11CC1020G1	S11CC1020MH	S09CC1022MH	211.7681	8
S09CC1022G1	S09CC1022MH	S09CC1023MH	257.3627	8
S11CC1006G1	S11CC1006MH	S11CC1020MH	237.3812	8

Observations & Photos

Obs_ID S1028-094-OB01

Address 3330 Dolfield Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11AA1005MH

Comments Smoke from cleanout in back yard. 3330 Dolfield Ave.



Picture \S1028-094-OB01-P01.jpg

Comments Back of house, 3330 Dolfield Ave.

Obs_ID S1028-094-OB02

Address 3334 Dolfield Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11AA1005MH

Comments Smoke from cleanout in back yard. 3334 Dolfield Ave.



Picture \S1028-094-OB02-P01.jpg

Comments Back of house, 3334 Dolfield Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-094	Smoke	9/2/2008	ADS/TM	S09CC1022MH	Dry	Yes	944.79

Obs_ID S1028-094-OB03

Address 3336 Dolfield Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11AA1005MH

Comments Smoke from cleanout in back yard. 3336 Dolfield Ave.



Picture \S1028-094-OB03-P01.jpg

Comments Back of house, 3336 Dolfield Ave.

Obs_ID S1028-094-OB05

Address 3346 Dolfield Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11CC1006MH

Comments Smoke from cleanout in back yard. 3346 Dolfield Ave.



Picture \S1028-094-OB05-P01.jpg

Comments Back of house, 3346 Dolfield Ave.

Obs_ID S1028-094-OB04

Address 3340 Dolfield Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S11CC1006MH

Comments Smoke from cleanout in back yard. 3340 Dolfield Ave.



Picture \S1028-094-OB04-P01.jpg

Comments Back of house, 3340 Dolfield Ave.

Obs_ID S1028-094-OB06

Address 3352 Dolfield Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11CC1020MH

Comments Smoke from cleanout in back yard. 3352 Dolfield Ave.



Picture \S1028-094-OB06-P01.jpg

Comments Back of house, 3352 Dolfield Ave.